THE COUNCIL FOR TOBACCO RESEARCH–U.S.A., INC.

September 27, 1974

To: W. U. Gardner, Scientific Advisory Board

Subject: Engineers Costs - Oak Ridge

During the past year extensive troubleshooting modifications, adaptations, etc. have been made to the Lorillard Machine. This has required extensive engineering manpower not anticipated in the original protocol. To date this has required shifting priorities in the program.

An engineering budget at $15,000, to be drawn down as required, through billing, is necessary to integrate timing circuits, animal holders, etc., and to continue troubleshooting when required for the Lorillard and Process & Instruments machines over the next six months.

J.H.K.

JHK:wg

1003536401

Source: https://www.industrydocuments.ucsf.edu/docs/nmyl0000

1003536402

PROCESS & INSTR.

Source: https://www.industrydocuments.ucsf.edu/docs/nmyl0000